

 CLEAN SYSTEMS SINGAPORE	FIELD SERVICE REPORT		Serial No.: CSS/
	HALF YEARLY PM (HPM)		CLEAN SYSTEM Technology (S) Pte Ltd 91 Defu Lane 10, #03-01, Singapore 539221 Tel: (065) 6369 0616 Fax: (065) 6286 0919
	Report No:	Customer ID:	
	Tool ID:	Model:	

CUSTOMER	Address:																				
	Contact Person:				Tel:																
Fault Reported:	HPM																				
Actual Fault:	Half Yearly Preventive Maintenance																				
Action Taken:	<p>As scheduled, performed half yearly preventive maintenance (HPM),</p> <p>-Disconnect old sensor from the system and install new sensor</p> <p>-Checked all parameters and alarms/warnings are reset</p> <p>-System handed over, running under normal working conditions</p> <p>-Replaced EPD sensor</p>																				
						<table border="1"> <tr><td>Tool ID</td><td></td></tr> <tr><td>Col. Exh. Pressure</td><td></td></tr> <tr><td>Cab. Exh. Pressure</td><td></td></tr> <tr><td>Inlet Pres. Before PM</td><td></td></tr> <tr><td>Inlet Pres. After PM</td><td></td></tr> <tr><td>Last Refill Date</td><td></td></tr> </table>	Tool ID		Col. Exh. Pressure		Cab. Exh. Pressure		Inlet Pres. Before PM		Inlet Pres. After PM		Last Refill Date				
Tool ID																					
Col. Exh. Pressure																					
Cab. Exh. Pressure																					
Inlet Pres. Before PM																					
Inlet Pres. After PM																					
Last Refill Date																					
Comments: Refer to attached checklist																					
WORKING HOURS																					
DAY	DATE: dd/mm/yy	Normal	Over Time	Night	Travel	Hotel															
MON						<input type="checkbox"/>															
TUE						<input type="checkbox"/>															
WED						<input type="checkbox"/>															
THU						<input type="checkbox"/>															
FRI						<input type="checkbox"/>															
SAT						<input type="checkbox"/>															
SUN						<input type="checkbox"/>															
TOTAL																					
Spares Replaced: KF Bellow - No. KF Bellow - No. KF40 'O' Rings - No.			<table border="1"> <tr> <td>Nature of work:</td> <td>Warranty <input type="checkbox"/></td> <td>Chargeable <input type="checkbox"/></td> </tr> <tr> <td>Maintenance <input type="checkbox"/></td> <td>Installation <input type="checkbox"/></td> <td>Commissioning <input type="checkbox"/></td> </tr> <tr> <td>Repair <input type="checkbox"/></td> <td>Callibration <input type="checkbox"/></td> <td>Modification <input type="checkbox"/></td> </tr> <tr> <td>Present status:</td> <td colspan="2">Handed over to customer <input type="checkbox"/></td> </tr> <tr> <td>Follow Up <input type="checkbox"/></td> <td>Under monitoring <input type="checkbox"/></td> <td>Job completed <input type="checkbox"/></td> </tr> </table>				Nature of work:	Warranty <input type="checkbox"/>	Chargeable <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Installation <input type="checkbox"/>	Commissioning <input type="checkbox"/>	Repair <input type="checkbox"/>	Callibration <input type="checkbox"/>	Modification <input type="checkbox"/>	Present status:	Handed over to customer <input type="checkbox"/>		Follow Up <input type="checkbox"/>	Under monitoring <input type="checkbox"/>	Job completed <input type="checkbox"/>
Nature of work:	Warranty <input type="checkbox"/>	Chargeable <input type="checkbox"/>																			
Maintenance <input type="checkbox"/>	Installation <input type="checkbox"/>	Commissioning <input type="checkbox"/>																			
Repair <input type="checkbox"/>	Callibration <input type="checkbox"/>	Modification <input type="checkbox"/>																			
Present status:	Handed over to customer <input type="checkbox"/>																				
Follow Up <input type="checkbox"/>	Under monitoring <input type="checkbox"/>	Job completed <input type="checkbox"/>																			
Engineer/s:			Customer:																		
Date:			Date:																		
Signature:			Signature/company stamp																		